Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	5	standard hot-plug controller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:03
S2	27	shpc	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 10:59
S3	111	(hot-plug or hot adj plug) adj controller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 10:59
S4	111	hot plug controller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:33
S5	41	hot-plug controller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF .	2005/08/24 11:00
S6	111	S5 or S4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:00
S7	11	standard hot plug controller	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:02
S8	3	(standard hot-plug controller) and (LED or light emitting diode)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:04
S9	2	(standard hot-plug controller) and (LED or light emitting diode) and pci	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:07
S11	3	(standard hot-plug controller) and (LED or light emitting diode)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:30

						·
S12	62	HPPC .	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ .	OFF	2005/08/24 11:33
S14	44	hot plug controller and LED	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:34
S15	35	hot plug controller and LED and register	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:53
S18	30	hot plug controller and LED and register and error	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:48
S19	25	hot plug controller and LED and register and error and command	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:48
S20	20	hot plug controller and LED and register and error and command and (duty cycle)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 11:50
S22	, 9	hot plug controller same LED	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:05
S23	3100	(blink\$3 or flash\$3) LED	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:05
S24	38	(blink\$3 or flash\$3) LED and hot plug	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:09
S25	29	(blink\$3 or flash\$3) LED and hot plug and rate	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:11

				-		
S29	16555	LED same (blink\$3 or flash\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:14
S31	36	LED same (blink\$3 or flash\$3) and 710/302/.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 13:15
S34	913	LED same (blink\$3 or flash\$3) same pattern	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:31
S35	458	LED same (blink\$3 or flash\$3) near3 pattern	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:31
S36	345	LED with (blink\$3 or flash\$3) near3 pattern	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:31
S37	230	LED near4 (blink\$3 or flash\$3) near3 pattern	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:32
538	156	LED near2 (blink\$3 or flash\$3) near2 pattern	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:35
S40	20	LED near2 (blink\$3 or flash\$3) near2 pattern same command	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:39
S41	36	LED near2 (blink\$3 or flash\$3) near2 pattern with indicat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:49
S42	0	pci slot indicators	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:50

				10:		
S43	0	pci slot indicator	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:50
S44	1045	pci slot	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:50
S45	16	pci slot near3 indicat\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:50
S48	4	pci slot with LED	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF .	2005/08/24 14:52
S49	4	pci slot with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 14:52
S55	1	blink\$4 same hard error	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/24 15:01
S56	9896	duty cycle with 50%	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 09:26
S57	1163	duty cycle with fifty percent	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF .	2005/08/26 09:26
S58	19	duty cycle with fifty percent same LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 09:27

S60	5	duty cycle with fifty with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 09:29
S61	2	change near2 speed with PCI bus	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:44
S62	0	(modify or vary) near2 speed with PCI bus	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:45
S63	58	enabl\$ with pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:46
S64	. 27	enabl\$ near4 pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:46
S65	7	enabl\$ near2 pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:55
S66	8	led with indicat\$ with state\$3 and 710/302	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:57
S67	. 12	led with indicat\$ with state\$3 and 710/302.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:55

S68	260	LED near2 indicat\$3 near2 error\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF ·	2005/08/26 14:58
S69	<b>82</b>	LED indicat\$3 near2 error\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:58
S70		LED indicat\$3 error\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:58
S71		LED near2 indicat\$3 near2 error\$3 same pci	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 14:58
S72	51756	SRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 15:39
S73 .		SRAM near3 coupled near2 bridge\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 15:40
S74		SRAM with coupl\$3 with bridg\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 15:41
S75	1125	error with indicat\$4 with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:07

S76	356	error with indicator with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:07
S77	34	error with indicator with LED with power	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 08:22
S78	6	power near3 error with indicator with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:09
S79	7	error with pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:12
S80	72	power with pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:12
S81		power with applied with pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:14
S82	6	power with up with pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/26 16:14
S83	19	bridge with error with LED	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 08:22

				•		·
S89	882	(blink\$4 or flash\$4) pattern	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 08:36
S90	23	(blink\$4 or flash\$4) pattern with error\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:39
S93	2	((blink\$4 or flash\$4) pattern) same pci	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:00
S94	2623	(blink\$4 or flash\$4) same pci	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:01
S95	19	(blink\$4 or flash\$4) same pci slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:01
S97	112090	power same slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:24
S98	4227	power near2 appl\$4 same slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:24
S99	490	power near2 appl\$4 with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:24

S10 0	330	power near2 applied with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:24
S10 1	220	power applied with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:24
S10 2	6	power applied with slot same pci	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 09:25
S10 3	194	(blink\$4 or flash\$4) indicat\$3 with error\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ ·	OFF	2005/08/29 09:39
S10 4	30	(error\$2 near2 occur\$3) same power with slot\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 10:01
S10 5		(error\$2 near2 occur\$3) with power with slot\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 10:03
S10 6	0	(error\$2 near2 occur\$3) same power with applied with slot slot\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 10:03
S10 7	8	power with applied with slot slot\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 10:03

S10 8	. 220	SRAM with bridge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 12:37
S11 0	23	SRAM with coupled with bridge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/29 12:42
S11 1	27	SRAM with coupl\$2 with bridge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ .	OFF	2005/08/29 12:42
S11 2	481240	(blink\$3 or flash\$3 or indicat\$3) same (error\$2 or problem\$2 or fault\$2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:55
S11 3	64644	(blink\$3 or flash\$3 or indicat\$3) same (error\$2 or problem\$2 or fault\$2) same power	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:55
S11 4	2347	(blink\$3 or flash\$3 or indicat\$3) same (error\$2 or problem\$2 or fault\$2) same power same slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:55
S11 5	301	(blink\$3 or flash\$3 or indicat\$3) same (error\$2 or problem\$2 or fault\$2) same power with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:56
S11 6	1,8	(blink\$3 or flash\$3) same (error\$2 or problem\$2 or fault\$2) same power with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:57

S11 7	105	indicat\$4 with (error\$2 or problem\$2 or fault\$2) same power with slot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:58
S11 8	134	indicat\$4 with (error\$2 or problem\$2 or fault\$2) with power with (slot or card)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/08/30 08:58